


[illegible]

**FIG. 1**




FIG. 2

SECRET 2322200

60




FIG. 3

80




FIG. 4






FIG. 5

Address List		Business
Abromowitz, Jeff	650-237-6349W	
Anderson, Mark	650-123-1234W	
Appleton, Sam	415-532-1253W	
Arlington, Ted	650-538-1632W	
Ash, Marilyn	650-860-1632W	
Attaboy, Kid	650-784-3263W	
Awshucks, Fred	792-867-1354W	
Balboa, Samuel	650-875-2351W	
Bixby, Bill	415-867-2302W	
Boomer, Bill	650-825-8302W	
Bundy, Melissa	415-386-3824W	
Look Up: <u>Boo.....</u>		<div>New</div> <div>   </div>

R: 5 GA

Address View		Business
<b>Bill Boomer</b>		
Senior Frisbee Thrower		
AussieLand Ltd.		
Work	408-352-3523	
Home	650-560-0768	
Fax	408-678-5863	
Pager	888-442-6649	
E-Mail	Boomer@aol.com	
Done	Edit	New

Fig 6B

The screenshot shows a mobile phone interface with a black header bar. On the left, it says "Address View" and on the right, "Business". Below the header, the contact's name "Bill Boomer" and title "Senior Frisbee Thrower" are displayed. A black bar with the word "Autodial" in white is below the contact info. The phone number "888-442-6649" is shown with a dotted line underneath. Below the number, it says "1 Prefix" with a dotted line. There are two checkboxes: the first is checked and labeled "Keep prefix as default", and the second is unchecked and labeled "Remove area code". At the bottom are two buttons: "OK" and "Cancel".

Address View Business

**Bill Boomer**  
Senior Frisbee Thrower

**Autodial**

888-442-6649

1 Prefix


☒ Keep prefix as default  
☐ Remove area code

OK Cancel

**Address View** **Business**

**Bill Boomer**  
Senior Frisbee Thrower


**Beam**

 **Searching...**

**Beam via**

**Infrared (IR)** **Radio (RF)**

**Cancel**





800 801 802 803 804 805 806

800




FIG. 8